TERMS OF REFERENCE A: DIMINUTION OF SOCIAL AMENITY

- Loss of community gathering places and streets/paths for cycling & walking
- Loss of shade & comfort & sense of place
- Impact on health & well-being (air quality & heat related morbidity)
- Impact of loss of trees on rise in water table in flood-prone area

TERMS OF REFERENCE B: APPROPRIATENESS & ADEQUACY OF FINANCIAL COMPENSATION

- Compensation due to breach of contract re tree protection
- \$ Value of large trees
- 10 year Arboriculture Maintenance program

TERMS OF REFERENCE C: EFFECTIVENESS OF THE GOVERNMENT'S COMMUNICATION WITH RESIDENTS

- Redacted GIPA
- Response to public meetings

TERMS OF REFERENCE D: OTHER MATTERS

Contract procedural issues



Saving Sydney's Trees Response to the Inquiry into the CSELR 2018

Document tendered by
Saving Sydney Trees Received by
Brett Rodgers
Date: 20 18 118
Resolved to publish Yes / No

1




'...diminution in social amenity for residents & the wider community caused by the project.


Maiden's Walk beside Alison Road - now gone!



Saving Sydney's Trees Response to the Inquiry into the CSELR 2018 Terms of Reference A: Compensation due to loss of community recreation spaces



ToR, A: Compensation due to loss of shade & potential heat-related morbidity





513 14 11

Problems and Symptoms caused by Hot Temperatures




Saving Sydney's Trees Response to the Inquiry into the CSELR 2018 Terms of Reference A: Compensation due to loss of shade & potential heat-related morbidity

4

Arboricultural Impact Assessment by KMH Environmental Pty Ltd, Oct 2015, revision 4

Appendix A: Compliance Matrix



Note <u>non-compliance</u> of branch protection and tree root compaction with heavy vehicle movement & storage of material within the TPZ root zone


MCoA B47B: Proponent shall employ construction techniques that <u>minimise</u> <u>impacts to tree root zones at all times along Anzac Parade</u> (its intersection with Alison Road), Alison Road and Wansey Road, including but not limited to those identified in environmental management measure T4 within table 4.2 of the Modification Report..





Saving Sydney's Trees Response to the Inquiry into the CSELR 2018 Terms of Reference B: Compensation due to breach of contract re tree protection These 2 trees were issued a DO NOT TOUCH order which <u>included their</u> <u>roots</u> in the Consent Conditions (B47)

Clearly there was <u>no</u> intention to comply with <u>B48 and B47</u> by ACCIONA or TfNSW.



6

"Tree Protection Zone fence should be located on a radius of 5.5M from the centre of the trunk. The TPZ can be contained by plastic bollards and connected with high visibility plastic tape. The base plates of the bollards should be pegged to the ground to prevent the line marking of the TPO from being altered." Arboricultural Impact Assessment Revision 7, 25/8/16, page 3



Saving Sydney's Trees Response to the Inquiry into the CSELR 2018 ToR B: Compensation due to breach of contract re tree protection




The orange plastic poles that demarcate the TPZ (Tree Protection Zone) have been moved inside the actual TPZ. The UTM Audit report, in all instances, indicates TPZ's are compliant. We question the reliability of these statements when evidence indicates the moving of these barricades for vehicle parking at

will. The Bulldozer working with in reach of the overhead limbs. This machine was witnessed impacting these limbs.



Saving Sydney's Trees Response to the Inquiry into the SELR 2018

ToR B: Compensation due to breach of contract re tree protection



Cahill Expressway – Ultimate ENDGAME due to root and branch damage



Saving Sydney's Trees Response to the Inquiry into the CSELR 2018

Compensation to ensure adequate care & avoid loss of remaining trees

Estimate for Remedial Tree works for CSELR Impact

Total \$10,920.00 per tree 800 trees = \$8,736,000.00 per year

10 year contract = \$80,736,000.00

- 1. Initial Ground & Aerial Inspection
- 2. Arboricultural Impact Assessment (AIA)
- 3. Root Mapping & Remediation
- 4. Bracing weakened branches by Cobra method
- 5. Selective pruning
- 6. Insect control
- 7. Fertilising & Weed Control
- 8. Electronic Monitored Irrigation



Best Practice Tree Management cobra - dynamic tree support system specially designed to be strong, gentle, flexible and shock-absorbing resulting from scientific research.

9



Saving Sydney's Trees Response to the Inquiry into the CSELR 2018

TERMS OF REFERENCE B: APPROPRIATE FINANCIAL COMPENSATION

Green Infrastructure for Cities -It's all about trees!!!

Amount of solar radiation canopy intercepts relates to canopy size, type and angle of leaves, depth & density of the canopy layers.

Tree attributes providing best shade include leaf area, high branching density, multiple canopy layers, canopy transmissivity, canopy size and projection and canopy ventilation.





Sydney's wonderful figs provide all the attributes needed.

Saving Sydney's Trees Response to the Inquiry into the CSELR 2018 Terms of Reference, B: Compensation to ensure health of remaining trees