

LENNOX HEAD PUBLIC SCHOOL - HEARING 09 MAY TENDER DOCUMENT



Portable classroom cluster



Air purifiers in some classrooms, mould build up, poor ventilation especially in the portable classroom cluster as windows are closed to minimise noise levels and mosquitoes.



One sheltered walkway from school hall to portable classroom cluster. Shelter ineffective during heavy rain.



Play space area fenced off due to artefact discovery



Unsheltered eating area



Image 1: Staffroom is located in a portable



Image 2: Staffroom is located in a portable



Canteen and music room located in a portable - exterior image



Canteen and music room located in a portable - interior image